




57 WEEKLY ROUNDUP

29 July - 5 August 2019




SECANT PILE WALL CONSTRUCTION



GROUND ANCHOR JOINT INSPECTION NRC, HANMI AND 57P



INFILTRATION WELLS FOR DEWATERING PROCESS



PROMOTING SAFE, CLEAN AND GREEN WORK ENVIRONMENT

